

Example of an arrangement of steel coil in aftermost cargo hold, showing the steel coils do not uniformly contact the hopper sloping plate.

