

## **SC74 Fire protection arrangements in cargo spaces including special category spaces**

(Rev.1  
2001)

Deleted in Nov 2005 because of SOLAS 2000 Amendments.



---

## **SC75 Fire protection arrangements in cargo spaces**

(Add.1  
2001)

(Rev.1  
Nov 2005)

(Reg. II-2/20.3.1.3)

The requirements to indicate any loss of ventilation capacity is considered complied with by an alarm on the bridge, initiated by fall-out of starter relay of fan motor.  
(MSC/Circ. 1120)



---

## **SC76 Engine bearing temperature monitors**

(Chapter II-1, Regulation 47.2 [1981])

The wording "or engine bearing temperature monitors" is understood to include all bearings i.e. journal and connecting rod bearings.



---

## **SC77 Cargo tanks overflow control system use of spill valves**

Deleted in Nov 2005 because of SOLAS 2000 Amendments.

