

SC74 Fire protection arrangements in cargo spaces including special category spaces

(Rev.1
2001)

Deleted in Nov 2005 because of SOLAS 2000 Amendments.



SC75 Fire protection arrangements in cargo spaces

(Add.1
2001)

(Rev.1
Nov 2005)

(Reg. II-2/20.3.1.3)

The requirements to indicate any loss of ventilation capacity is considered complied with by an alarm on the bridge, initiated by fall-out of starter relay of fan motor.
(MSC/Circ. 1120)



SC76 Engine bearing temperature monitors

(Chapter II-1, Regulation 47.2 [1981])

The wording "or engine bearing temperature monitors" is understood to include all bearings i.e. journal and connecting rod bearings.



SC77 Cargo tanks overflow control system use of spill valves

Deleted in Nov 2005 because of SOLAS 2000 Amendments.

