

No. 135 **Rooms for emergency fire pumps in cargo ships**

(June 2014)

The room(s) where the pump and prime mover are installed should have adequate space for maintenance work and inspections.

End of Document