
SC168 Hydrants for dangerous goods

(June 2002)
(Rev.1
Nov 2005)

(SOLAS 2000 Amendments (MSC.99(73)), Reg.II-2/19.3.1.2)

The number and position of hydrants should be such that at least two of the required four jets of water, when supplied by single lengths of hose, may reach any part of the cargo space when empty; and all four jets of water, each supplied by single lengths of hose may reach any part of ro-ro cargo spaces.

(MSC/Circ. 1120)

Note: This UI SC 168 is to be uniformly implemented by IACS Members and Associates from 1 January 2003.

